


Manufacturing Problem: OEE

1. The mold machine has been measured as being able to make 1100 good scissors per day. Calculate its OEE.

2. In the absence of "good parts" measurements, set the OEE for all other equipment to 85%. Check the resulting capacity and see if customer demand can be met.



Units	Year	Week	Week
	52	70	5
	Week	Hr	day

Manufacturing Solution: OEE

1. The mold machine has been measured as being able to make 1100 good scissors per day. Calculate its OEE.

2. In the absence of "good parts" measurements, set the OEE for all other equipment to 85%. Check the resulting capacity and see if customer demand can be met.

