


Manufacturing Problem: Changeover

The product family consists of four sizes of scissors, necessitating changeovers at the Mold Handles activity. Each changeover takes 60 minutes. Is there adequate capacity on the Mold Handles activity to meet demand for each scissor size every day? Weekly



Manufacturing Solution: Changeover

The product family consists of four sizes of scissors, necessitating changeovers at the Mold Handles activity. Each changeover takes 60 minutes. Is there adequate capacity on the Mold Handles activity to meet demand for each scissor size every day? Weekly

